



21433 SW Oregon Street
Sherwood, Oregon 97140 U S A
Tel (503) 625-2560 • Fax (503) 625-5132

PARTS MARKETING BULLETIN

DATE: November 8, 2005

BULLETIN NO. _____ PMB0501

PAGE: 1 of 1

MODEL(S): _____ All Cranes

ATTENTION: ENGINEERING OFFICERS

SUBJECT: REPLACEMENT SWING DRIVE BRAKE

Swing Drive Brake (P/N 228011) is no longer available and has been replaced by P/N 236885. The replacement brake is interchangeable **as an assembly ONLY**.

Because of internal differences between the two part numbers, you **MUST** replace your existing parts coverage to assure there will not be a delay in receiving correct internal brake components in the future.

Please replace the existing parts coverage with the attached coverage of 236885 upon receipt of this bulletin.