

DATE: 2-1-83

PAGE: 1 of 1

REV: ---

BULLETIN NO.: E0124

SECTION: Engine (02)

MODEL(S): All Units

SUBJECT: RADIATOR FILL PROCEDURES

Daily inspection of the radiator water level is recommended. Cooling systems utilizing the Anti-Aeration Radiator Baffles restrict visual observation of the true water level - although water can be seen, the cooling system may not be full. To gain a true fill, add water slowly up to the bottom of the fill neck and allow a (30) second settling period.

Remember to compensate for the loss of anti-freeze when adding water. Inspect the radiators daily for restriction caused by bark dust, paper, and other foreign materials.

INTERCHANGEABILITY

Not applicable

PARTS STOCK

Not applicable

EFFECTIVE SERIAL NUMBERS

Not applicable

For questions or concerns, please contact Allied Systems Company Service Department at (503) 625-2560.