

DATE: August 1, 2013

PAGE: 1 of 1

BULLETIN NO .: WSB0401

SECTION: 6-2 (Components)

MODEL(S): Logstackers,

Chipdozers, and Steelworkers

ATTENTION: WAGNER DEALERS, PARTS AND SERVICE MANAGERS

SUBJECT: INFORMATIONAL BULLETIN FOR UPDATED RECALIBRATION INSTRUCTIONS FOR FUEL SENDERS WITH PART NUMBERS 230729 AND 585978.

Allied Systems Company has recently updated our calibration instructions (link to form [80-939](#)) to the most current revision for the fuel senders used in our Logstackers, Chipdozers, and Steelworkers. Should recalibration of these senders be needed, please use these updated instructions.

Parts affected:

P/N 230729 (Logstackers & Chipdozers)

P/N 585978 (Steelworker)

For questions or concerns, please contact Allied Systems Company Service Department at (503) 625-2560.