




NOTE: TERMINALS WITH THE SAME NUMBER IN THE CB PANEL AND OVERHEAD SHOULD BE CONNECTED.



