


Strobe Light Warning



9
3
2
1

SEE "ANSI SCHEMATIC MAGNET CONTROL" DRAWING FOR WIRING DETAIL. ITEMS 10, 11, 18, 19 & 20 ARE NOT SHOWN.



Strobe Light Warning

Item	Part No.	Qty	Description	Item	Part No.	Qty	Description
	580419		Strobe Light Warning				
1	00103340	6	. Flat Washer	14	232910	1	. Relay Spring
2	18498W	3	. Capscrew	15	229428	1	. Resistor
3	R13811190	3	. Locknut	16	228776	1	. Terminal Ring
4	204916	2	. Clip	17	219404	8'	. Wire
5	Y27E-06	4	. Washer	18	219436	2'	. Wire
6	242420	1	. Light, Blue Strobe	19	237628	2'	. Wire
7	221964	1	. Terminal	20	189-0076	2	. Terminal Lug
8	221965	1	. Terminal	21	R13813167	2	. Machine Screw
9	529118	1	. Bracket, Light	22	238437	2	. Nut, Esna
10	236924	1	. Terminal Block	23	219390	23'	. Loom, Auto
11	236926	1	. Jumper, Horizontal	24	213916	24	. Grommet
12	231290	1	. Socket	25	R13811191	4	. Locknut
13	242793	1	. Relay				